

JT600 Mini-USB port Driver Installation



V1.2

Shenzhen joint technology co,;ltd

04-26-2011

1 install "Mini-USB cable driver.exe"

Copy JT600 relative documents from CD, and find "Mini-USB cable driver.exe",and install it.



2 Connect the Mini-USB cable with PC



Please note this COM port number .you need this number when configure the JT600 parameters.

